

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

(Domestic) / Import Vehicles

CAMPAIGN No.	5 1 7 5	DATE	July. 1 2 . 2 0 2 2
MANUFACTURER	YAMAHA MOTOR CO., LTD.		
DESCRIPTION OF DEFECT	<p>(1) For safety components, interior and exterior components, and other components fitted for public road travel, the component or its mounting unit, if falling short of the required evaluation, may lose their function due to unlit lighting devices, detached or broken parts, or similar events and, in a worst-case scenario, may result in a vehicle failing to meet the safety standards.</p> <p>(2) Some gearbox main shaft oil seals fail to seal lubricating oil in the gearbox due to insufficient airtightness. Hence, if continuously used as is, the oil seal may ooze and drip lubricating oil onto the road surface.</p> <p>(3) The accelerator return spring for the accelerator pedal has insufficient strength. Hence, if continuously used as is, the spring may snap and break and, in a worst-case scenario, may fail to return the accelerator pedal completely, and the parking brake failure during manual driving.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
組立	「APP」	2 0 2 0 ~ 2 0 2 1	2
組立	「AR-04」	2 0 1 5 ~ 2 0 2 2	43
組立	「AR-05」	2 0 1 7 ~ 2 0 2 1	10
組立	「AR-07」	2 0 1 7 ~ 2 0 2 1	71
組立	「YG-M」	2 0 1 7 ~ 2 0 2 0	9
組立	「YG-ML」	2 0 1 8 ~ 2 0 2 0	18
組立	「YG-ML+」	2 0 1 8	1
TOTAL			1 5 4