

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN NO.	5 1 8 1	DATE	July13.2022
MANUFACTURER	NICHIGO CORPORATION		
DESCRIPTION OF DEFECT	<p>In the electrical equipment of rotary snowplows, Due to improper wiring fixing method, The starter motor wiring rub against the wiring clamp due to running vibration. and the coating may be damaged. Therefore, if it is continued to be used as it is, a short circuit between the damaged part and the clamp, and in the worst case, a fire may occur.</p>		
TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
YDR-R09E	KBR108	2017~2022 R09E-0002~ R09E-0077	73
YDR-R10E	HTR88	2017~2022 R10E-0002~ R10E-0126	120
		TOTAL	193

【Notes】 The scope of the chassis number of the recalled vehicles, there is a case where the vehicle that do not qualify are also included.