

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN NO.	5 1 8 2	DATE	July13.2022
MANUFACTURER	NICHIGO CORPORATION		
DESCRIPTION OF DEFECT	In the electrical equipment of rotary snowplows, Since the wiring is improperly fixed, if the wiring is continued to be used as it is, the starter motor wiring and the wiring clamp may be rubbed by vibration, and the coating may be damaged, resulting in a short circuit and, in the worst case, it may lead to a fire.		
TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
YDR-R08E	HTR148	2018~2022 R08E-0002~ R08E-0065	61
		TOTAL	61

【Notes】 The scope of the chassis number of the recalled vehicles, there is a case where the vehicle that do not qualify are also included.