

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5185	DATE	Jul.12 2022
MUNUFACTURER	Mitsubishi Fuso Truck and Bus Corporation		
DESCRIPTION OF DEFECT	<p>On some heavy-duty and medium-duty trucks with air suspension, the rear axle shock absorber mounting bolts and nuts are not tightened to the specified torque because they were tightened with an inappropriate tool. If the vehicle continues to be used in this condition, the bolts and nuts in question may loosen. In the worst case, the bolts and nuts in question will fall off, and for medium-duty trucks, a shock absorber may interfere with an ABS sensor harness and cause the ABS to stop operating.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2KG-FS74HZ	「FUSO SUPER GREAT」	2021~2021	5
2KG-FU74HZ		2021	1
2PG-FP74GGR		2021	1
2PG-FP74HDR		2021~2021	29
2PG-FP74HER		2021~2021	6
2PG-FS74HZ		2021~2021	22
2PG-FS75HZ		2021~2021	4
2PG-FU74GZ		2021~2021	3
2PG-FU74HZ		2021~2021	12
2PG-FU75HZ		2021~2021	4
2PG-FV74HZ		2021~2021	6
2PG-FY74HY		2021~2021	2
2KG-FK65FY		「FUSO FIGHTER」	2021~2021
2KG-FK65FZ	2021~2021		4
		TOTAL	101