

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5183	D A T E	Jul.21. 2022
MANUFACTURER	SUBARU CORPORATION		
DESCRIPTION OF DEFECT	In the back lamp switch (back lamp), due to improper material of components, black coating or corrosion may occur on contact point inside the switch. Therefore, if it is continued to be used, the back lamp may not light up.		

T Y P E	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
CBA-VBA	「WRX」	2015~2020	22,841
TOTAL			22,841