

## VEHICLE SAFETY/ POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicle

CAMPAIGN No.	5186	DATE	July 22, 2022
MANUFACTURER	Komatsu Ltd.		
DESCRIPTION OF DEFECT	<p>The protective material that protects the electrical wiring harness routed to the bottom of the forklift motor is inadequate. There is a possibility that dust which is rolled up during operation, may enter through the gaps in the protective material. If used as it is, the wiring harness will be worn by rubbing against dust due to engine vibration, etc. If the harness breaks, an error of low charging voltage will appear. Alternatively, the forklift cannot be restarted after the engine is stopped. And in the worst case, the wiring harness and other metal parts may come into contact with each other to generate heat, resulting in fire.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
YDR-M289	「FH100-1」 「FH120-1」 「FH135-1」 「FH160-1」	2018-2022	55
TOTAL			55