

## VEHICLE SAFETY/ POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicle

CAMPAIGN No.	5187	DATE	July 22, 2022
MANUFACTURER	Komatsu Ltd.		
DESCRIPTION OF DEFECT	The O-ring contact surface in some Shovel Loader brake pipe is widely machined due to improper machining dimensions of the portion that connects to the differential housing. Possibility of insufficient sealing ability of brake oil, resulting in oil leak due to pressure applied during brake operation.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
YDN-WA139	「WA80-8」	2019-2022	705
		TOTAL	705