

VEHICLE SAFETY/ POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicle

CAMPAIGN No.	5188	DATE	July.22,2022
MANUFACTURER	TADANO LTD.		
DESCRIPTION OF DEFECT	<p>On some cranes, the snap rings on the axle shaft may be not attached due to manufacturing error. Therefore, if the crane is continued to be used as it is, noise caused by the bearing cup in the joint coming loose. In the worst case, the crane may become unable to travel.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
YDS-T014	「GR-160N-4」	2021-2022	63
YDS-T018	「GR-160N-5」	2022	1
		TOTAL	64