

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5191	DATE	Jul.22 2022
MANUFACTURER	KATO WORKS CO.,LTD.		
DESCRIPTION OF DEFECT	In the power transmission device of the wheel cranes, there is possibility that the snap ring of the joint part is not installed because of improper axle shaft assembly process. Therefore, if the vehicle continuing travel, an abnormal noise may occur due to the bearing cup of the joint part coming out and the vehicle may not be able to travel in the worst case.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	Note
YDS-KRC017	KR-25H	2021~2022	146	
YDS-KRC018	KR-80H	2021~2022	64	
YDR-KRC020	KRM-13H(M)	2021~2022	58	
YDS-KRC024	KR-60H	2021~2022	29	
YDR-KRC022	KRM-13H(M)	2021~2022	28	
YDS-KRC016	KR-50H	2021~2022	24	
YDS-KRC023	KRM-35H	2021~2022	19	
YDS-KRC021	KRM-25H	2022~2022	1	
TOTAL			369	