

VEHICLE SAFETY RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5190	DATE	Jul. 28, 2022
MANUFACTURER	SUZUKI MOTOR CORPORATION		
DESCRIPTION OF DEFECT	<p>Due to the improper structure of the air flow selector mechanism in the manual heating and air conditioning unit, the internal linkage parts may be dislocated and the air flow selector may become inoperative, if the air flow selector knob is quickly turned under high temperature condition.</p> <p>As the result, the defroster function may become inoperative and the visibility through the front windshield may be obstructed.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES	NOTE
3BD-DA17V 5BD-DA17V	EVERY	2022	5,149	Vehicles with manual A/C
3BD-DR17V 5BD-DR17V	NV100 CLIPPER		3,045	
3BD-DG17V 5BD-DG17V	SCRUM		443	
3BD-DS17V 5BD-DS17V	MINICAB		374	
		TOTAL	9,011	