

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5 1 9 2	DATE	July. 28. 2022
MANUFACTURER	N I S S A N		
DESCRIPTION OF DEFECT	<p>In the electric brake booster, if frequent braking operations are repeated under severe usage condition, the electric wire inside the pump motor is damaged due to the inappropriate specifications of the hydraulic pump motor and the required hydraulic pressure is insufficient and then the brake warning light is turned on, after that the warning sound is activated. If continues to be driven on this condition, in worst case, the braking effect may become poor.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
DAA-HT32	X-TRAIL	2015	11,724
DAA-HNT32		~ 2019	44,884
		TOTAL	56,608