

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5194	DATE	August. 30. 2022
MANUFACTURER	SHINMAYWA INDUSTRIES, LTD.		
DESCRIPTION OF DEFECT	On vehicles such as dump trucks, installation of reverse warning lights and rear combination lights is inappropriate, thus the installation angle of reverse warning lights, brake lights, tail lights, rear reflector and direction indicators does not respectively comply with the requirements prescribed in safety standards.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
GD-S200P	HIJET	1999~2001	16
GM-S200P		2001~2005	20
GM-S210P		2002~2016	16
TE-S200P		2005~2008	26
TE-S210P		2005~2010	86
EBD-S201P		2008~2015	143
EBD-S211P		2008~2016	158
EBD-S500P		2015~2021	182
EBD-S510P		2015~2021	131
3BD-S500P		2021~2022	32
3BD-S510P		2021~2022	29

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
EBD-S510U	PIXIS	2016	1
3BD-S500U		2021	1
3BD-S510U		2021	1
EBD-S211J	SAMBAR	2012~2015	123
EBD-S500J		2017~2019	4
EBD-S510J		2015~2021	42
3BD-S510J		2021~2022	6
		TOTAL	1017

The affected parts shipped as kits, but the vehicles with them installed, cannot be identified.

PARTS	MODEL	SERIAL NUMBERS AND DELIVERY PERIOD OF PARTS SHIPPED AS KITS	NUMBER OF KITS
DUMP BODY KIT	DR-0**	1985~1998	220
		1998~2002	29
		2005~2016	25
	DR0-0004SD	2016~2022	56
	DRG1-00S	1985	2
	DT-03	1985~1998	15
	GD1-9*	1988~1997	15
		1998~2001	4
DETACHABLE BODY SYSTEM KIT	CCA03-10	2003~2015	17
		TOTAL	383