

VEHICLE SAFETY RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5195	DATE	Sep. 1, 2022
MANUFACTURER	SUZUKI MOTOR CORPORATION		
DESCRIPTION OF DEFECT	Due to the improper control of the manufacturing process of an IC (Integrated Circuit) in the engine controller, the IC internal circuit may break, resulting in the engine starting failure or the engine stalling while driving.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
EBD-DA16T	CARRY	2015~2016	31,276
EBD-DR16T	NT100 CLIPPER		5,997
EBD-DG16T	SCRUM		1,707
EBD-DS16T	MINICAB		2,939
		TOTAL	41,919