

VEHICLE SAFETY RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5196	DATE	Sep. 8, 2022
MANUFACTURER	SUZUKI MOTOR CORPORATION		
DESCRIPTION OF DEFECT	<p>The Positive Crankcase Ventilation valve in the engine blow-by gas recirculation system may have been press-fitted improperly.</p> <p>Due to the above, the engine oil may leak as the sealing material deteriorated after certain period of vehicle use. In the worst case, the leaked oil may drip onto the exhaust system, resulting in a fire incident.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES	
5AA-FF21S	IGNIS	2022	4	
5BA-MA27S	SOLIO		13	
5AA-MA37S			28	
5AA-ZC43S	SWIFT		1	
5AA-ZC53S			2	
4BA-ZC83S 5BA-ZC83S			4	
5AA-MB37S	DELICA D:2		11	
			TOTAL	63