VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN NO.	5199	DATE	September 9 ,2022
MANUFACTURER		ISUZU MOTORS LIMITED	
MANUFACTURER DESCRIPTION OF DEFECT		On certain vehicles equipped with E13C engines, due to inappropriate DPR regeneration control program, the urea SCR catalyst temperature becomes higher than assumed during DPR regeneration under high-revolution and high-load conditions, which may accelerate the progress of catalyst deterioration. Therefore, if the vehicle is used under the condition continually, the emission value of nitrogen oxides in the exhaust gas may exceed the regulation value.	

ТҮРЕ	COMMERCIAL NAME	MODELYEAR RECALLED	NUMBER OF VEHICLE
2RG-RU1ESDJ	[ISUZU GALA]	2017-2022	493
		TOTAL	493