

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5200	DATE	Sep.9 2022
MANUFACTURER	KATO WORKS CO.,LTD.		
DESCRIPTION OF DEFECT	<p>In wheel crane engines, due to improper engine control program, the air flow sensor recognizes the amount of air taken in from the air cleaner lower than that of actual amount and the exhaust gas recirculation (EGR) amount would be reduced causing nitrogen oxides in the exhaust gas may exceed the regulated value.</p> <p>Due to improper urea water injection control program, when the performance of the urea SCR catalyst reduces, the proper amount of urea water cannot be injected, and nitrogen oxides in the exhaust gas may exceed the regulated value.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	Note
YDS-KRC018	KR-80H	2017~2022	661	
TOTAL			661	