

VEHICLE SAFETY RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5215	DATE	Sep. 22, 2022
MANUFACTURER	SUZUKI MOTOR CORPORATION		
DESCRIPTION OF DEFECT	The defective parts of the force-limiter were installed in the winding device in the front seat belt assembly for the spare parts supply. The force-limiter may fail to operate properly and the seat belt may be pulled out in the event of the collision and it may fail to satisfy the legal requirement of the occupant protection.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
EBD-DA63T	CARRY	2009~2011	2
TA-HN22S	KEI	2002	1
		TOTAL	3