

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5216	DATE	Oct.6.2022
MANUFACTURER	TOYOTA		
DESCRIPTION OF DEFECT	<p>#1. In the curtain shield airbag[CSA], due to improper work operation at the vehicle assembly plant, there is a possibility that the auxiliary strap for CSA deployment may have been incorrectly installed to the correct location. In this condition, the CSA may not deploy properly during its activation, in the worst case, vehicle occupant(s) may have a risk of injury.</p> <p>#2. In the mounting area of the disc wheels, due to improper disc wheels manufacturing and hub bolt design specifications, there is a possibility that the clamping force of the hub bolts is insufficient for the driving performance of the vehicle. In this condition, if the vehicle is operated repeatedly with a series of rapid acceleration and deceleration, the bolts could be loosen. If the vehicle continues to be operated in this condition, abnormal noise could occur, and in the worst case, tires could separate from the vehicle.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ZAA-XEAM10	[bZ4X]	2022	42
ZAA-YEAM15			70
ZAA-XEAM10X	[SOLTERRA]	2022	10
ZAA-YEAM15X			82
		TOTAL	204