VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5217	DATE	Oct.6.2022
MANUFACTURER	ТОУОТА		
DESCRIPTION OF DEFECT	In the hybrid system, due to an improper programming, there is a possibility that the vehicle will not enter a failsafe driving mode if a temporary slip occurs in the input damper of the hybrid transaxle during sudden acceleration and warning lights are illuminated. If this were to occur, the hybrid system will shut down.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
6AA-MXPH10	[YARIS]	2019-2020	31,674
6AA-MXPH15			6,000
		TOTAL	37,674