

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	R5218	DATE	2022/10/12
MANUFACTURE	Niigata Transys co.ltd.		
DESCRIPTION OF DEFECT	In the brake fluid leak alarm device, the low oil level warning light does not turn on even if the amount of brake fluid drops below the specified value due to an inappropriate control program.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
YDS-NR6B	NR303	2021	5
		TOTAL	5