

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5220	DATE	October. 13. 2022
MANUFACTURER	HONDA MOTOR CO., LTD.		
DESCRIPTION OF DEFECT	In the locking device's electric handle, the lock pin position setting in the handle locking mechanism is not appropriate and the strength of the components is insufficient, so the component gears may be impacted and damaged if the lock pin does not enter the lock hole when the handle is locked. As a result, the lock pin may become stuck, and in the worst case, the handle lock may not be able to be locked or unlocked.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
8BL-RH10	「X-ADV」	2021~2022	1,307
		TOTAL	1,307