

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5222	DATE	Oct.19 2022
MANUFACTURER	KATO WORKS CO.,LTD.		
DESCRIPTION OF DEFECT	<p>In electric equipment of wheel cranes, the selection of the cable connection terminal connected to the high current fuse is inappropriate. Therefore, if you continue to use it,</p> <p>(1) The cable connection terminal fixing bolt may become loose, contact may become poor, the battery may not be charged, the charging warning light may turn on, and in the worst case, the vehicle may not be able to drive.</p> <p>(2) Increase of the electrical contact resistance of the cable terminal connection may cause the cable connection terminal to generate heat, melt the fuse holder, and in the worst case, it may a fire.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	Note
YDS-KRC016	KR-50H	2016~2022	699	
YDS-KRC017	KR-25H	2016~2022	1,201	
YDS-KRC024	KR-60H	2021~2022	24	
KA4120	—	2019~2022	29	
KA5161	—	2020~2022	9	
TOTAL			1,962	