Domestic Vehicles

CAMPAIGN No.	5219	DATE	October 20, 2022
MANUFACTURER	DAIHATSU		
DESCRIPTION OF DEFECT	In the steering gear, due to improper sealing of the boot mounting area and its location, which is directly beneath the drain hose of the air conditioner, the condensed water from the air conditioner may drip onto the mounting area and enter inside the gear. Therefore, if a vehicle with this condition is continuously used, rust may generate inside the gear and cause abnormal noises. In the worst case, the bearing may be damaged and the steering may not be controllable.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
3BD-S321V	HIJET	2019–2020	43,569
5BD-S321V			
EBD-S321V			
HBD-S321V			
3BD-S331V			22,926
5BD-S331V			
EBD-S331V			
HBD-S331V			
3BD-S321W	HIJET DECKVAN		1,024
EBD-S321W			
3BD-S331W			1,731
EBD-S331W			
3BA-S321G			2,643
ABA-S321G	ATRAI WAGON		
3BA-S331G			1,782
ABA-S331G			1,102

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
3BD-S321B			
5BD-S321B			2214
EBD-S321B			2214
HBD-S321B	SAMBAR	2019–2020	
3BD-S331B			1992
EBD-S331B			
HBD-S331B			
3BD-S321Q	SAMBAR OPENDECK		13
EBD-S321Q			
EBD-S331Q			53
ABA-S321N	DIAS		110
ABA-S331N			133
3BD-S321M			5448
5BD-S321M			
EBD-S321M	PIXIS VAN		
HBD-S321M			
3BD-S331M			2845
5BD-S331M			
EBD-S331M			
HBD-S331M			
·		TOTAL	86,483