## VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN No.	5211	DATE	24 Oct, 2022	
MANUFACTURER	MITSUBISHI MAHINDRA AGRICULTURAL MACHINERY CO.,LTD.			
DESCRIPTION OF DEFECT	On the wiring harness in the meter panel of agricultural tractors, some wiring harnesses are in contact with the plate—on which the brake pedal return spring hangs due to improper protective instructions in the wiring harness drawing.  As a result, vibration during traveling damages the wiring harness due to its wear. And it causes a short circuit in the internal wires of the wiring harness. In the worst case, the wiring harness may burn out, resulting in a fire.			
TYPE	COMMERCIAL	MODEL	NUMBER OF	
	NAME	YEAR RECALLED	VEHICLE	
YDM-GT36G	$\lceil \mathrm{GM}302 \rfloor$	2021,2022	3	
	「GM332」	2021,2022	9	
	ГСМЗЗ2НЈ	2021,2022	10	
	「GM362」	2021,2022	13	
	ГСМ362НЈ	2021,2022	5	
	「GM362HU」	2021	10	
YDM-GT36F	「GA302」	2021	5	
	ГGА302Н 」	2021,2022	2	
	$\lceil \text{GA}332 \rfloor$	2021,2022	5	
	ГGА332Н 」	2021,2022	8	
	「GAK332」	2021	2	
	「GA362」	2021,2022	27	
	ГGА362Н 」	2021,2022	33	
	「GAK362」	2021,2022	12	
YDM-GT50H	「GM452D」	2021,2022	6	
	「GM502D」	2021,2022	14	
	「GM502ET」	2021,2022	3	

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
YDM-GT55E	「GM552D」	2021,2022	31
YDM-GT50G	$\lceil \mathrm{GA452} \rfloor$	2021,2022	14
	「GAK452」	2021,2022	3
	「GA502」	2021,2022	25
	「GAK502」	2021,2022	6
YDM-GT55D	「GA552」	2021,2022	62
	「GAK552」	2021,2022	19
		TOTAL	327