

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/ Import Vehicles

CAMPAIGN No.	5212	DATE	24 Oct, 2022
MANUFACTURER	MITSUBISHI MAHINDRA AGRICULTURAL MACHINERY CO.,LTD.		
DESCRIPTION OF DEFECT	Due to the incorrect design of the turn unit of the direction indicator, the driver is not alerted when the direction indicator has a malfunction, such as a short circuit or others. As a result, there is a risk that the driver may continue to drive without noticing the malfunction of the direction indicator.		
TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
EDM-VC46A	「VY446」	2015	129
EDM-VC33C	「VY434」	2015	100
	「VS334」	2015	53
	「VS329」	2015	56
YDM-VC35A	「V435」	2016~2020	244
	「V335」	2016~2019	177
	「V435A」	2020~2021	134
	「V335A」	2020~2021	71
VC25A	「V325」	2015~2020	200
	「V325A」	2020~2021	106

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
GT25G	「GOE25」	2015~2022	915
YDM-GT36G	「GM332W」	2021	5
YDM-GT36D	「GM330W」	2018~2020	42
EDM-GT46F	「GA41」	2014~2015	41
	「GA46」	2015	26
EDM-GT50D	「GA50」	2014~2015	103
	「GAK50」	2014~2015	20
EDM-GT28E	「GA28」	2015	9
EDM-GT36C	「GA30」	2015	31
	「GA30H」	2014~2015	7
	「GA32」	2014~2015	33
	「GA32H」	2014~2015	17
	「GAK32」	2015	4
	「GA36」	2015	65
	「GA36H」	2014~2015	58
	「GAK36」	2015	20
EDM-GT46E	「GX371」	2014~2015	25
	「GX401」	2014~2015	24
	「GX461」	2014~2015	44
EDM-GT34F	「GO261」	2014~2015	165
	「GO261H」	2014~2015	7
	「GO281」	2014~2015	74
	「GO281H」	2014~2015	8
	「GO301」	2014~2015	95
EDM-GT34F	「GO301H」	2014~2015	19
	「GO321」	2014~2015	43
	「GO321H」	2015	4
	「GO341」	2014~2015	77
	「GO341H」	2014~2015	32
EDM-GT30F	「GJ27D」	2014~2015	21
	「GJ30D」	2014~2015	25
		TOTAL	3329