VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5227	DATE	October 27, 2022
MANUFACTURER	DAIHATSU		
DESCRIPTION OF DEFECT	Some repair parts of front seat belt retractor for the subject vehicles may have the force limiter with manufacturing defect. Therefore, it is possible that the force limiter does not function properly and the seat belt is pulled out in the event of collision and so on, and that the vehicles does not conform to the occupant protection performance requirement specified in the safety regulations.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-L675S	Mira Cocoa	2010-2017	4
		TOTAL	4