

VEHICLE SAFETY/ POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicle

CAMPAIGN No.	5225	DATE	November 1, 2022
MANUFACTURER	Komatsu Ltd.		
DESCRIPTION OF DEFECT	Some shovel loaders are assembled with axles manufactured based on incorrect heat treatment instructions. Therefore, if the vehicle is continued to be used as it is, the bolts that fix the axle shaft may loosen, causing hydraulic oil to leak, and in the worst case, the axle shaft may come off, resulting in a loss of travel.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
YDN-WA139	「WA80-8」	2019-2019	9
		TOTAL	9