

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5229	DATE	Nov.10.2022
MANUFACTURER	TOYOTA		
DESCRIPTION OF DEFECT	<p>In the replacement parts of front seatbelt equipped with force limiter*, due to incorrect manufacturing control of a shaft assembled with the seatbelt retractor, there is a possibility that the shaft may have abnormal shape. In this condition, when the force limiter is activated to protect the occupants in the event of a crash, the seat belt extended further than intended, which could cause the occupant's restrain force to reduce.</p> <p>* Force limiter; A function that reduces the impact on the occupant's chest by loosening the seat belt gradually maintaining the restrain force of the seat belt to be a certain level in the event of a collision.</p>		

The affected parts shipped as repair parts, and could possibility the vehicles equipped with them.

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
UA-ZNE10G	[WISH]	2003	7
UA-ANE10G		2003	1
CBA-ZNE14G		2005	1
DAA-NHW20	[PRIUS]	2006-2008	3
UA-ACU30W	[HARRIER]	2003	1
CBA-ACU35W		2012	1
CBA-ACU25W	[KLUGER V]	2004	1
DBA-GRS182	[CROWN]	2006	1
CBA-NNP11	[PORTE]	2009	1
UA-UZZ40	[SOARER]	2001-2002	3
DBA-UZZ40	[SC430]	2005	1
		TOTAL	21

The affected parts shipped as repair parts, and could not possibility the vehicles equipped with them.

PARTS NAME	PARTS NO.	SHIPMENT YEAR	NUMBER OF PARTS	NOTE	
Seatbelt RH	73210-68010	2022	11	[WISH]	
	73210-48072		2	[HARRIER]	
	73210-52720		1	[PORTE]	
	73210-22580		1	[MARK X]	
	73210-30892		6	[CROWN]	
Seatbelt LH	73220-30852			2	
	73220-30862			1	
	73220-18020			1	[86GRMN]
			TOTAL	25	