

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5232	D A T E	Nov.10. 2022
MANUFACTURER	SUBARU CORPORATION		
DESCRIPTION OF DEFECT	In the front seat belt retractor which is replacement repair parts, since the internal components of force limiter mechanism was improperly manufactured, some may have a defective shape. Therefore, when the force limiter engages in the event of a crash, the length of the belt pulled out may be longer than normal, and in the worst case, restraining force of occupants may be reduced.		

Estimated vehicles assembling the affected front seat belt as a repair part.

	T Y P E	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
Subaru	DBA-BS9	「Legacy」	2015~2020	5
	DBA-BN9		2017	2
	4BA-BS9		2020	1
	DBA-ZC6	「BRZ」	2013~2018	3
Toyota	DBA-ZN6	「86」	2012	2
	4BA-ZN6		2021	1
			TOTAL	14

Affected repair part that has not been identified in the market.

AFFECTED PART	PART NUMBER	SHIPPING PERIOD OF TARGET COMPONENTS	AFFECTED REPAIR PART NUMBER
Front Seat Belt ASSY	64620AL000	Jun.11, 2022 ~ Sep.12, 2022	12
	64620AL010		
	64620CA010		TOTAL

Improvement action will be taken for vehicles with the affected repair part.