## VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

**Domestic Vehicles** 

CAMPAIGN No.	5243	DATE	November 17, 2022	
MANUFACTURER	Mazda Motor Corporation			
DESCRIPTION OF	On the oil pump chain of the engine, due to inappropriate procedure			
DEFECT	of installation in production process, the chain may not be installed on			
	the correct position. Therefore, the chain may come off and the oil			
	pump may be stopped. Because the oil pressure may decrease, the oil			
	pressure warning light and engine warning light may illuminate, and			
	the engine output may be limited. In the worst case, the engine may			
	seize up.			

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
3CA-KH3R3P	Mazda 「CX-60」	2022	20
		Total	20