

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN NO.	5235	DATE	November 24 ,2022
MANUFACTURER		ISUZU MOTORS LIMITED	
DESCRIPTION OF DEFECT		Regarding the recall No. 5156 filed on June 2, 2022, a wrong fixing clip has been attached to the battery cable in question due to an inappropriate description in the manual for inspecting and replacing the cable. If used as is, the coating of the said cable may be worn due to engine vibration, and consequently the strands may be exposed and short-circuited. In the worst case, the engine may not start.	

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2KG-LV290N3 2RG-LV290N3	[ERGA]	2021-2022	44
2RG-LV290Q3 2TG-LV290Q3		2021-2022	10
2KG-LR290J4	[ERGA MIO]	2021-2022	30
		TOTAL	84