VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5230	DATE	Nov. 28th, 2022
MANUFACTURER	KUBOTA Corporation		
DESCRIPTION OF DEFECT	In agricultural tractor direction indicators, the blinking state does not change when the front or rear direction indicators do not function properly because the power consumption of the bulbs used for the side direction indicators is inappropriate. This does not comply with Japanese safety standards.		
TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
-	ГМ7131」	2015~2016	15
	ГМ7151」	2015~2016	39
	ГМ7171」	2015~2016	42
YDR-M7001	「M7-131」	2016~2018	58
	「M7-151」	2016~2018	139
	「M7-171」	2016~2017	69
不明	「M7-131」	2018	1
	「M7-171」	2016~2017	17
YDR-M7002	ГМ7-132」	2019~2022	86
	ГМ7-152」	2019~2022	155
	ГМ7-172」	2019~2022	108
不明	ГМ7-172」	2019~2020	2
	1	TOTAL	731

[Notes]

The range of vehicle numbers for recalled vehicles may include vehicles that are not.