## VEHICLE SAFETY/ POLLUTION RECALL CAMPAIGN IN JAPAN

## Domestic Vehicle

CAMPAIGN No.	5239	DATE	Nov.30,2022			
MANUFACTURER	TADANO LTD.					
DESCRIPTION OF DEFECT	On some cranes, the engine cover and coolant hose may be contacted due to manufacturing error.  Therefore, if the crane is continued to be used as it is, the coolant hose is damaged and engine coolant may leak out.  In the worst case, the crane may become unable to travel by engine overheating.					

TYPE	COMMERCIAL NAME		MODEL YEAR RECALLED	NUMBER OF VEHICLES
YDS-T018	「GR-160N-5」	2022		19
			TOTAL	19