

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5247	DATE	Nov.30.2022
MANUFACTURER	TOYOTA		
DESCRIPTION OF DEFECT	In a dual stage inflator of the driver's front air bag, due to an insufficient moisture absorption protection for the propellant in the inflator, there is a possibility that the propellant may degrade due to repeated moisture absorption and desorption by temperature cycling. In this condition, the inflator could rupture in the event of the deployment of the airbag.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
UA-AZT250 CBA-AZT250	[AVENSIS]	2003-2006	2,366
CBA-AZT251		2005-2006	315
UA-AZT255 CBA-AZT255		2003-2006	545
UA-AZT250W CBA-AZT250W	[AVENSIS WAGON]	2003-2006	1,498
CBA-AZT251W		2005-2006	247
UZ-AZT255W CBA-AZT255W		2003-2006	444
		TOTAL	5,415