

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5238	DATE	December 1, 2022
MANUFACTURER	DAIHATSU		
DESCRIPTION OF DEFECT	<p>On vehicles equipped with a compact tail lift, the left rear combination lamp may reach a high temperature during continuous hill climbing due to improper setting of the exhaust pipe outlet.</p> <p>Therefore, if the vehicle is continuously used in this condition, the resin portion of the lamp may melt, and in the worst case, the lamp may not be lit.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
3BD-S500P	HIJET TRUCK	2021-2022	82
3BD-S510P			183
TOTAL			265