

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5 2 4 1	DATE	Dec. 1. 2022
MANUFACTURER	N I S S A N		
DESCRIPTION OF DEFECT	In the engine control computer, the warning lamp may not illuminate in specific OBD requirements due to the improper setting of warning lamp lighting for OBD.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
LDF-VW2E26	N V 3 5 0 C A R A V A N	2 0 1 2 ~ 2 0 2 1	5 4, 1 0 0
LDF-VW6E26			4 1, 4 1 7
LDF-CW4E26			4, 5 6 7
LDF-CW8E26			1 0, 7 7 5
LDF-DW4E26			1, 0 5 1
LDF-JVW2E26	I S U Z U C O M O		1, 0 7 1
LDF-JVW6E26			8 9 3
LDF-JCW4E26			1 1 0
LDF-JCW8E26			1 2 1
LDF-JDW4E26			1 0
		TOTAL	1 1 4, 1 1 5