

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN NO.	5244	DATE	December 1 ,2022
MANUFACTURER	ISUZU MOTORS LIMITED		
DESCRIPTION OF DEFECT	In some exhaust gas recirculaton (EGR) coolers, fins are not brazed to the exhaust passage (i.e. tubes) due to improper fin material. Continued operation of the vehicle in this condition may lead to cracks in the tubes, which could allow exhaust gas to enter the coolant passage. This may cause cooling failures and, in the worst case, overheating.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	
2PG-FRR90S1□ 2PG-FRR90S2□ 2PG-FRR90T2□ 2RG-FRR90S1□ 2RG-FRR90S2□ 2RG-FRR90T2	[FORWARD]	2021-2022	5,040	
2PG-FRS90S2□ 2RG-FRS90S2		2021-2022	72	
2PG-FSR90S2□ 2PG-FSR90T2□ 2RG-FSR90S2□ 2RG-FSR90T2		2021-2022	779	
2PG-FSS90S2□ 2RG-FSS90S2		2021-2022	25	
2PG-FTR90U2□ 2PG-FTR90V2□ 2RG-FTR90U2□ 2RG-FTR90V2		2021-2022	903	
2PG-FTS90S2		2022	1	
2PG-FVR90U2		2021-2022	19	
2KG-FVZ90U2		2021	9	
2KG-LV290N3□ 2RG-LV290N3□ 2TG-LV290N3		[ERGA]	2021-2022	144
2RG-LV290Q3□ 2TG-LV290Q3			2021-2022	35
2KG-LR290J4	[ERGA MIO]	2021-2022	109	

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2PG-BRR90S1 <input type="checkbox"/> 2PG-BRR90S2 <input type="checkbox"/> 2PG-BRR90T2 <input type="checkbox"/> 2RG-BRR90S1 <input type="checkbox"/> 2RG-BRR90S2 <input type="checkbox"/> 2RG-BRR90T2	[CONDOR]	2021-2022	252
2RG-BRS90S2		2021	1
2PG-BSR90S2 <input type="checkbox"/> 2PG-BSR90T2 <input type="checkbox"/> 2RG-BSR90S2 <input type="checkbox"/> 2RG-BSR90T2		2021-2022	48
2PG-BTR90U2 <input type="checkbox"/> 2PG-BTR90V2 <input type="checkbox"/> 2RG-BTR90U2 <input type="checkbox"/> 2RG-BTR90V2		2021-2022	54
2PG-BVR90U2		2021-2022	2
2KG-BVZ90U2		2021	1
		TOTAL	7,494

Vehicles Which Had The Affected Parts Installed After They Rolled Off The Assembly Line

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2PG-FRR90S1 <input type="checkbox"/> 2PG-FRR90S2 <input type="checkbox"/> 2PG-FRR90T2 <input type="checkbox"/> 2RG-FRR90S1 <input type="checkbox"/> 2RG-FRR90S2 <input type="checkbox"/> 2RG-FRR90T2	[FORWARD]	2018-2021	44
2PG-FRS90S2		2020	1
2RG-FSR90S2		2019-2020	2
2RG-FTR90U2 <input type="checkbox"/> 2RG-FTR90V2		2018	2
2PG-FVR90U2		2021	1
TRG-NHR85AN		[ELF]	2015
TPG-NHS85AN <input type="checkbox"/> TRG-NHS85A		2015-2018	10
TPG-NJR85AD <input type="checkbox"/> TPG-NJR85AN <input type="checkbox"/> TRG-NJR85A		2015-2018	8

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	
SKG-NJS85A□ TKG-NJS85A□ TKG-NJS85AN	[ELF]	2011-2013	4	
SKG-NKR85N□ TPG-NKR85AD□ TPG-NKR85AN□ TPG-NKR85N□ TPG-NKR85R□ TRG-NKR85A□ TRG-NKR85AR□ TRG-NKR85R		2011-2019	27	
TKG-NKR85YN		2016-2017	2	
TDG-NKS85AD□ TDG-NKS85AN□ TPG-NKS85A□ TPG-NKS85AN		2012-2019	6	
TPG-NLR85AN□ TRG-NLR85AN□ TRG-NLR85AR		2014-2019	19	
TPG-NLS85AN□ TRG-NLS85AN		2017-2019	2	
TPG-NMR85AN□ TPG-NMR85N□ TRG-NMR85AN□ TRG-NMR85N		2015-2017	8	
TDG-NMS85AN□ TKG-NMS85AR□ TPG-NMS85AN		2013-2019	5	
TPG-NPR85AN□ TPG-NPR85AR□ TPG-NPR85N□ TRG-NPR85AN□ TRG-NPR85AR□ TSG-NPR85AN		2014-2019	94	
TKG-NPR85YN□ TPG-NPR85YN		2014-2017	24	
TKG-NPS85AN□ TPG-NPS85AN□ TPG-NPS85AR		2015-2019	12	
2DG-LV290N2□ 2KG-LV290N2□ 2PG-LV290N2		[ERGA]	2017-2019	30
2DG-LV290N3□ 2PG-LV290N3			2019-2020	3

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2KG-LR290J3	[ERGA MIO]	2017-2019	3
TRG-LPR85AN	[TITAN]	2016	1
		TOTAL	309

The Affected Parts Shipped As Repair Parts, But The Vehicles With Them Installed, Cannot Be Identified.

PARTS NAME	PARTS NO.	SHIPMENT YEAR	NUMBER OF □ VEHICLE
EGR Cooler	8-98063283-8 8-98181205-1 8-98340161-0 8-98340161-1 8-98352272-0 8-98352272-1	2021-2022	312
4HK1 ENGINE	8-98334318-0 8-98390189-0	2021-2022	3
4JJ1 ENGINE	1-87110250-0 1-87110260-0 5-87110098-0 5-87110099-0 5-87110100-0 5-87110101-0 8-98217869-0 8-98256658-0	2021-2022	119
		TOTAL	434