

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	5245	DATE	Dec. 1. 2022
MANUFACTURER	Hino Motors, Ltd.		
DESCRIPTION OF DEFECT	In some exhaust gas recirculation (EGR) coolers, fins are not brazed to the exhaust passage (i.e. tubes) due to improper fin material. Continued operation of the vehicle in this condition may lead to cracks in the tubes, which could allow exhaust gas to enter the coolant passage. This may cause cooling failures and, in the worst case, overheating.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2KG-KR290J4	[HINO Rainbow]	2021~2022	65
2KG-KV290N3	[HINO BlueRibbon]	2021~2022	22
2TG-KV290N3			
2RG-KV290Q3		2021~2022	14
2TG-KV290Q3			
		TOTAL	101

Vehicles which had the affected parts installed after they rolled off the assembly line.

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2KG-KR290J3	[HINO Rainbow]	2018	2
2DG-KV290N2	[HINO BlueRibbon]	2018	1
2TG-KV290Q2		2019	1
		TOTAL	4

The affected parts shipped as repair parts, but the vehicles with them installed, cannot be identified.

PARTS NAME	PARTS NO.	SHIPMENT YEAR	NUMBER OF PARTS
EGR Cooler	SX00117382	2021~2022	10
	SX00119549		
	SX00117406		
	SX00119550		
		TOTAL	10