## VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

**Domestic Vehicles** 

CAMPAIGN No.	5249	DATE	December 8,2022		
MANUFACTURER	MITSUBISHI MOTORS CORPORATION				
DESCRIPTION OF DEFECT	The spare parts catalogue contains errors in the part numbers resulting in the supply of incorrect spare parts (Driver seat belt Steering column, and Driver airbag), and before-approval parts may be assembled. As a result, in the worst case scenario, the performance of occupant protection could be compromised.				

ТҮРЕ	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
5AA-B34W	「eK」	2019	1
4AA-B35W		2020	1
5BA-B36W		2019~2020	4
4AA-B38W		2020	1
4AA-B38A	「eK SPACE」	2020	1
4AA-B45W	「DAYZ」	2019~2020	9
5BA-B46W		2019~2020	3
5AA-B47W		2020	4
4AA-B48W		22020	4
5AA-B44A	「ROOX」	2021	2
		TOTAL	30

The parts for which the vehicle can not be identified because it was shipped as service parts

Part Name	Part No.	Delivery Period of the part	Quantity
STEERING COLUMN	48811-7MA4B	$2021 \sim 2022$	2
DRIVER SEATBELT	86884-7MA0A	2021	3