

## VEHICLE SAFETY/ POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicle

CAMPAIGN No.	5258	DATE	December 8, 2022
MANUFACTURER	Komatsu Ltd.		
DESCRIPTION OF DEFECT	In the exhaust pipes of some shovel loaders, there are cases where cracks occur due to vibrations during operation, etc., because of insufficient strength of the joint parts (V-shaped joints) connecting the exhaust pipes. Therefore, if the machine continues to be used as it is, there is a possibility that the V-shaped joint is broken and exhaust gas leaks from the gap.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
YDP-WA138	「WA100-8」	2017-2022	2976
YDP-WA138	「WA150-8」	2019-2022	351
YDP-WR005	「WR12-8」	2021-2022	5
TOTAL			3332