

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/Import Vehicles

CAMPAIGN No.	5254	DATE	Dec. 9, 2022
MANUFACTURER	Kawasaki Motors, Ltd.		
DESCRIPTION OF DEFECT	The plunger in the camshaft-chain tensioner can lock up during usage due to deterioration of internal parts. Continuous use in this condition can result in loss of engine power during use.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	Notes
2BL-ZXT02A	Ninja H2 SX Ninja H2 SX SE Ninja H2SX SE+	2018~2021	2178	
2BL-ZXT02J	Ninja H2 CARBON	2019~2021	311	
2BL-ZRT00K	Z H2 Z H2 SE	2020~2022	996	
8BL-ZXT02P	Ninja H2 SX Ninja H2 SX SE	2022	704	
TOTAL			4,189	