

**VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN
JAPAN**

Domestic Vehicles

CAMPAIGN No.	5259	DATE	December 21, 2022
MANUFACTURER	SUZUKI MOTOR CORPORATION		
DESCRIPTION OF DEFECT	<p>The wiring harness for the ignition switch is bent hard when the steering is turned fully due to improper fixed position of the wiring. If the motorcycle is kept using, repeated bending may break the wiring, and in the worst case, the engine may stop and be unable to restart.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
SUZUKI	GIXXER	2021 ~ 2022	3,632
		TOTAL	3,632