

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	R5169	DATE	Dec.23.2022
MANUFACTURE	Kworks Co.,Ltd		
DESCRIPTION OF DEFECT	Due to improper consideration of the strength of the frame, there are places where the strength of the frame is insufficient. As a result, cracks or deformation may occur due to vibrations or the like during running, and in the worst case, the frame may break, making it impossible to run.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
TWJ40L	TrailWorks	2019	2
TWJ52L	TrailWorks	2020~2022	6
		TOTAL	8 units