

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5260	DATE	December 23, 2022
MANUFACTURER	DAIHATSU		
DESCRIPTION OF DEFECT	<p>Regarding forward recognition cameras for the preventive safety function, the adhesive strength of camera bracket to the windshield glass is weak in some cases due to the improper adhesion process control. Therefore, the bracket with camera may come off from the windshield glass during driving. This may interrupt driver's forward view and may not satisfy the standard in the worst case. Also, the edge shape of camera bracket may not satisfy the standard required.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-LA150S	MOVE	2017-2019	64,833
DBA-LA160S			14,553
DBA-LA250S	CAST		46,150
DBA-LA260S			9,782
5BA-M700S	Boon		6,843
5BA-M710S			1,341
DBA-LA150F	STELLA		5,244
DBA-LA160F			2,495
DBA-LA250A	PIXIS JOY		6,971
DBA-LA260A			1,572
5BA-M700A	PASSO		27,410
5BA-M710A			5,395
		TOTAL	192,589