

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5263	DATE	Dec.28 2022
MANUFACTURER	KATO WORKS CO.,LTD.		
DESCRIPTION OF DEFECT	Due to improper vehicle design, the side guard (entanglement preventive device) of the vacuum truck does not meet the safety standards for the distance from the rear end of the front tire to the front end of the side guard. So, extend the front end of the side guard so that the distance (Front tire/ Side guard) to meet the safety standards.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	Note
2KG-FD2ABA	RANGER	2018~2022	36	
2KG-FK62FE4	FIGHTER	2020	1	
TOTAL			37	