

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / ~~Import Vehicles~~

CAMPAIGN No.	5274	DATE	January 24, 2023	
MANUFACTURER	UD Trucks Corporation			
DESCRIPTION OF DEFECT	With regards to vehicles equipped with Lane Change Support (LCS) and UD Active Steering System, due to the inappropriate Driver Assistance Control Unit (DACU) program setting, when the LCS identify a vehicle on the left side and the driver activates left direction indicator, Lane Departure Prevention (LDP) and Lane Departure Warning System (LDWS) will not be cancelled. Thus, the vehicle is departing from the original lane, the LDP activates warning buzzer and steering intervention, also, the LDWS activates warning lamp and buzzer.			
TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	
2RG-CG5EA	Quon	2022	2	
2PG-CG4FA		2022	4	
2PG-CG5FA 2RG-CG5FA		2022	246	
2PG-GK5DAB 2RG-GK5DAB		2022	135	
		TOTAL		387