

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	5267	DATE	2023/1/25
MANUFACTURE	Niigata Transys co.ltd.		
DESCRIPTION OF DEFECT	Because of improper installation of piping between the urea tank and the urea pump, prevent the generation of the urea water pressure required to operate the aftertreatment device (SCR system). As a result, the aftertreatment device does not operate normally, and in the worst case, harmful gases in the exhaust gas would be discharged without being treated.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
YDR-NR3C	NR84	2022	7
YDR-NR3C	NR144	2022	5
		TOTAL	12