

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5 2 6 8	DATE	Jan. 27. 2023
MANUFACTURER	N I S S A N		
DESCRIPTION OF DEFECT	In the ECO motor for vehicle with Idling Stop system, due to inappropriate seal specification of bearing in the unit, it may be broken with contamination which coming into bearing, and it may make the abnormal noise. If continue to be driven on this condition, in worst case, the engine may be stalled due to ECO motor breakage. Then, if the unexpected flammables (for example; spilled oil) adhere on the surrounding parts, flammables might burn due to spark and hot air from the opening of ECO motor, and in the worst case, it may lead to a thermal incident.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
DBA-FC26	N I S S A N S E R E N A	2 0 1 0 ~ 2 0 1 6	70, 181
DBA-FNC26			28, 046
DBA-NC26			14, 193
DBA-C26			27, 934
DBA-NT32	N I S S A N X T R A I L	2 0 1 3 ~ 2 0 1 7	102, 788
DBA-T32			32, 282
DBA-SNC26	S U Z U K I L A N D Y	2 0 1 0 ~ 2 0 1 6	857
DBA-SC26			1, 181
		TOTAL	277, 462