

VEHICLE SAFETY/ POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicle

CAMPAIGN No.	5275	DATE	February 3, 2023
MANUFACTURER	Komatsu Ltd.		
DESCRIPTION OF DEFECT	In some shovel loader fuel injection systems, the axial force of the bolt that fixes the pressure control valve (PCV) to the supply pump is insufficient. As a result, the bolt may loosen due to the force acting on the supply pump, such as vibration transmitted from the fuel pipe or the pressure of the pumped fuel.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
UDS-WA120	「WA470-7」	2013-2016	50
YDS-WA129	「WA470-8」	2017-2022	71
YDS-WA142	「WA470-10」	2020-2022	37
TOTAL			158