

VEHICLE SAFETY/ POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicle

CAMPAIGN No.	5 2 7 6	DATE	February 3, 2023
MANUFACTURER	SAKAI HEAVY INDUSTRIES, LTD.		
DESCRIPTION OF DEFECT	In a grader fuel injection system, the bolt holding the pressure control valve (PCV) to the supply pump has insufficient axial force. Therefore, the bolt may loosen due to force acting on the supply pump, such as vibration transmitted from the fuel pipe and the pressure of the pumped fuel. In the worst case, it leads to the bolt may break, causing fuel leak from the supply pump.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
YDS-1ER13	ER555F	2017 - 2022	143
		TOTAL	143